

FILE COPY

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
EXECUTIVE SUMMARY

Amenia Rte 22 South Site
Site Name

NYD980641559
EPA Site ID Number

Route 22 South
Amenia, Dutchess County, NY
Address

02-8612-11
TDD Number

DRAFT

SITE DESCRIPTION

Amenia Route 22 South Site is an inactive municipal dump approximately ten acres in size, located on the west side of Route 22 in the Town of Amsterdam, Dutchess County, New York. The dump opened at an unknown time and received municipal wastes from the towns of Amsterdam, New York and Sharon, Connecticut. The northern portion is currently owned by Karl Saliter of Sharon, Connecticut and the southern portion is owned by John Segalla of Amsterdam, New York. The dump has changed owners in the past and has been closed and expanded several times. According to a New York Department of Conservation (DEC) report the site was closed in 1975. Drums were reported to have been buried and the site is suspected of receiving industrial wastes from the area.

A site inspection was conducted on February 25, 1987. Three groundwater samples, four soil samples, two surface water and two sediment samples were taken. The analytical data has not been received.

HAZARD RANKING SCORE: Pending analytical results.

Prepared by: Pauline Doherty
of NUS Corporation

Date: 5/20/87

295864



POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 1 - SITE LOCATION AND INSPECTION INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site)

02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER

Amenia Route 22 South Site
03 CITY

Route 22 South

Amenia
09 COORDINATES

04 STATE 05 ZIP CODE 06 COUNTY 07 COUNTY CODE 08 CONG DIST.
NY 12501 Dutchess 027

LATITUDE

LONGITUDE

10 TYPE OF OWNERSHIP (Check one)

4 10 5 1' 0 0" N

0 7 30 3 3' 3 0" W

X A. PRIVATE B. FEDERAL C. STATE
D. COUNTY E. MUNICIPAL F. OTHER
G. UNKNOWN

III. INSPECTION INFORMATION

01 DATE OF INSPECTION

02 SITE STATUS

03 YEARS OF OPERATION

02 / 25 / 87
MONTH DAY YEAR

ACTIVE
X INACTIVE

BEGINNING YEAR / 1975 X UNKNOWN
ENDING YEAR

AGENCY PERFORMING INSPECTION (Check all that apply)

A. EPA X B. EPA CONTRACTOR NUS Corporation
(Name of firm)
E. STATE F. STATE CONTRACTOR
(Name of firm)

C. MUNICIPAL D. MUNICIPAL CONTRACTOR
(Name of firm)
G. OTHER (Specify)

05 CHIEF INSPECTOR

06 TITLE

07 ORGANIZATION

08 TELEPHONE NO.

Gary Bielen
09 OTHER INSPECTORS

Environmental Scientist
10 TITLE

NUS Corporation
11 ORGANIZATION

(201) 225-6160
12 TELEPHONE NO.

Jane Bullis

Environmental Scientist

NUS Corporation

(201) 225-6160

John Ducar

Geologist

NUS Corporation

(201) 225-6160

Roberta Riccio

Environmental Scientist

NUS Corporation

(201) 225-6160

Dan deBruijn

Chemist

NUS Corporation

(201) 225-6160

DRAFT

13 SITE REPRESENTATIVES INTERVIEWED

14 TITLE

15 ADDRESS

16 TELEPHONE NO.

Gerald Wilcox

Foreman

Amenia, New York

(914) 373-8151

17 ACCESS GAINED BY
(Check one)

18 TIME OF INSPECTION

19 WEATHER CONDITIONS

X PERMISSION
WARRANT

0900

Sunny, 15-20°F, Wind 0-5 mph.

IV. INFORMATION AVAILABLE FROM

01 CONTACT

02 OF (Agency/Organization)

03 TELEPHONE NO.

Diana Messina

U.S.EPA, Region 2, Edison, NJ

(201) 321-6776

04 PERSON RESPONSIBLE FOR SITE INSPECTION FORM

05 AGENCY

06 ORGANIZATION

07 TELEPHONE NO. 08 DATE

Gary Bielen

U.S.EPA

NUS Corporation

(201) 225-6160

4 / 10 / 87
MONTH DAY YEAR

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 2 - WASTE INFORMATION

I. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. WASTE STATES, QUANTITIES, AND CHARACTERISTICS

01 PHYSICAL STATES (Check all that apply)		02 WASTE QUANTITY AT SITE	03 WASTE CHARACTERISTICS (Check all that apply)		
<input checked="" type="checkbox"/> A. SOLID	<input type="checkbox"/> E. SLURRY	(Measures of waste quantities must be independent)	<input type="checkbox"/> A. TOXIC	<input type="checkbox"/> E. SOLUBLE	<input type="checkbox"/> I. HIGHLY VOLATILE
<input type="checkbox"/> B. POWDER, FINES	<input checked="" type="checkbox"/> F. LIQUID		<input type="checkbox"/> B. CORROSIVE	<input type="checkbox"/> F. INFECTIOUS	<input type="checkbox"/> J. EXPLOSIVE
<input type="checkbox"/> C. SLUDGE	<input type="checkbox"/> G. GAS		<input type="checkbox"/> C. RADIOACTIVE	<input type="checkbox"/> G. FLAMMABLE	<input type="checkbox"/> K. REACTIVE
<input type="checkbox"/> D. OTHER	(Specify) _____		<input type="checkbox"/> D. PERSISTENT	<input type="checkbox"/> H. IGNITABLE	<input type="checkbox"/> L. INCOMPATIBLE
		TONS _____	<input type="checkbox"/> M. NOT APPLICABLE		
		CUBIC YARDS _____			
		NO. OF DRUMS <u>3</u>			

III. WASTE TYPE Unknown

CATEGORY	SUBSTANCE NAME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS
SLU	SLUDGE			
OLW	OILY WASTE			
SOL	SOLVENTS			
PSD	PESTICIDES			
OCC	OTHER ORGANIC CHEMICALS			
IOC	INORGANIC CHEMICALS			
ACD	ACIDS			
BAS	BASES			
MES	HEAVY METALS			

IV. HAZARDOUS SUBSTANCES (See Appendix for most frequently cited CAS Numbers)

CATEGORY	02 SUBSTANCE NAME	03 CAS NUMBER	04 STORAGE/DISPOSAL METHOD	05 CONCENTRATION	06 MEASURE OF CONCENTRATION
----------	-------------------	---------------	----------------------------	------------------	-----------------------------

Unknown

DRAFT

V. FEEDSTOCKS (See Appendix for CAS Numbers)

CATEGORY	01 FEEDSTOCK NAME	02 CAS NUMBER	CATEGORY	01 FEEDSTOCK NAME	02 CAS NUMBER
FDS	Unknown		FDS		
FDS			FDS		
FDS			FDS		
FDS			FDS		

VI. SOURCES OF INFORMATION (See specific references. e.g., state files, sample analysis, reports)

NUS Corp. Site Inspection conducted on 2/25/87 under TDD# 02-8612-11, Edison, NJ.
New York Department of Conservation (DEC) Background File.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 X A. GROUNDWATER CONTAMINATION 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 3823 04 NARRATIVE DESCRIPTION

The potential exists for the unconfined aquifer to be contaminated. There are no impermeable zones between ground surface and aquifer of concern.

01 X B. SURFACE WATER CONTAMINATION 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 0 04 NARRATIVE DESCRIPTION

The potential exists for the contaminants to flow from the landfill into an unnamed tributary of the Wassaic Creek which is situated adjacent to the site.

01 C. CONTAMINATION OF AIR 02 X OBSERVED (DATE: 2/25/87) POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 3823 04 NARRATIVE DESCRIPTION

Air contamination was observed during the site inspection. OVA readings from the northern portion of the site are documented in the field logbook.

01 X D. FIRE/EXPLOSIVE CONDITIONS 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION

Since the potential contaminants are unknown, fire and explosive conditions cannot be ruled out.

01 X E. DIRECT CONTACT 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 1183 04 NARRATIVE DESCRIPTION

A potential does exist because the site is not fenced so people could come in contact with the drums and/or suspected industrial wastes deposited on site.

01 X F. CONTAMINATION OF SOIL 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 AREA POTENTIALLY AFFECTED: Approximately 10 (ACRES) 04 NARRATIVE DESCRIPTION

The potential exists for the contamination of soil. The buried landfill may have leached into the soil.

01 X G. DRINKING WATER CONTAMINATION 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 3823 04 NARRATIVE DESCRIPTION

The unconfined aquifer in the area is used for drinking water and there are no impermeable zones in the area.

01 H. WORKER EXPOSURE/INJURY 02 OBSERVED (DATE:) POTENTIAL ALLEGED
03 WORKERS POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION

No potential exists because the site is inactive.

01 I. POPULATION EXPOSURE/INJURY 02 OBSERVED (DATE:) X POTENTIAL ALLEGED
03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION

The drinking water can be potentially affected. The surface water in the area is used for recreational purposes and may also be affected.

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☒ J. DAMAGE TO FLORA 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION

A potential exists due to the drums and the suspected industrial wastes that possibly was deposited on site. These substances could migrate offsite and affect the trees, shrubs and marsh areas which are found adjacent to the site.

01 ☒ K. DAMAGE TO FAUNA 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION (Include name(s) of species)

A potential exists for damage to fauna. Contaminants emanating from the site may affect aquatic organisms in the stream and small mammals which inhabit the area.

01 ☒ L. CONTAMINATION OF FOOD CHAIN 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION

A potential exists due to the suspected industrial wastes possibly deposited on site and the drums that were found there. These substances could be migrating into the stream and affecting various fish species. These substances can bioaccumulate in the food chain.

01 ☒ M. UNSTABLE CONTAINMENT OF WASTES 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
(Spills/runoff/standing liquids/leaking drums)
03 POPULATION POTENTIALLY AFFECTED: 1183 04 NARRATIVE DESCRIPTION

A potential exists due to the suspected industrial wastes that may have been deposited on site. The site has no liner.

01 ☒ N. DAMAGE TO OFFSITE PROPERTY 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION

The potential for damage to offsite property exists. Contaminants could leach into the unnamed tributary of the Passaic Creek which is adjacent to the site. Since it flows offsite, various properties in the area could be affected.

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs 02 ☐ OBSERVED (DATE: _____) ☐ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION

A potential doesn't exist because the site is in a rural area and there are no sewers, storm drains or WWTPs located near the site.

01 ☒ P. ILLEGAL/UNAUTHORIZED DUMPING 02 ☐ OBSERVED (DATE: _____) ☒ POTENTIAL ☐ ALLEGED
04 NARRATIVE DESCRIPTION

A potential exists due to the lack of fencing surrounding the site.

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

III. TOTAL POPULATION POTENTIALLY AFFECTED: 3823

IV. COMMENTS

V. SOURCES OF INFORMATION (Cite specific references. e.g., state files, sample analysis, reports)

New York Department of Conservation (DEC) Background File
NUS Corporation Site Inspection conducted on 2/25/87 under TDD# 02-8612-11, Edison, NJ.
Telecon between H. Norbin, Amenia Town Supervisor, and P. Doherty.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 4 - PERMIT AND DESCRIPTIVE INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. PERMIT INFORMATION

01 TYPE OF PERMIT ISSUED
(Check all that apply)

02 PERMIT NUMBER

03 DATE ISSUED

04 EXPIRATION DATE

05 COMMENTS

☐ A. NPDES

☐ B. UIC

☐ C. AIR

☐ D. RCRA

☐ E. RCRA INTERIM STATUS

☐ F. SPCC PLAN

☐ G. STATE (Specify)

☐ H. LOCAL (Specify)

☐ I. OTHER (Specify)

☐ J. NONE

DRAFT

III. SITE DESCRIPTION

01 Storage/Disposal
(Check all that apply)

02 AMOUNT

03 UNIT OF MEASURE

04 TREATMENT
(Check all that apply)

05 OTHER

☐ A. SURFACE IMPOUNDMENT

☐ B. PILES

☒ C. DRUMS, ABOVE GROUND

☒ D. TANK, ABOVE GROUND

☐ E. TANK, BELOW GROUND

☐ F. LANDFILL

☐ G. LANDFARM

☐ H. OPEN DUMP

☐ I. OTHER

(Specify)

3

1

55-gallon

☐ A. INCINERATION

☐ B. UNDERGROUND INJECTION

☐ C. CHEMICAL/PHYSICAL

☐ D. BIOLOGICAL

☐ E. WASTE OIL PROCESSING

☐ F. SOLVENT RECOVERY

☐ G. OTHER RECYCLING/RECOVERY

☐ H. OTHER

(Specify)

☐ A. BUILDINGS ON SITE

zero

06 AREA OF SITE

Approximately 10
(Acres)

07 COMMENTS

IV. CONTAINMENT

01 CONTAINMENT OF WASTES (Check one)

☐ A. ADEQUATE, SECURE

☐ B. MODERATE

☒ C. INADEQUATE, POOR

☐ D. INSECURE, UNSOUND, DANGEROUS

02 DESCRIPTION OF DRUMS, DIKING, LINERS, BARRIERS, ETC.

During our inspection three 55 gallon drums were found. The site has no liners or other means to properly contain the wastes.

V. ACCESSIBILITY

01 WASTE EASILY ACCESSIBLE:

☒ YES

☐ NO

02 COMMENTS

No fences surround the site so waste is easily accessible.

VI SOURCES OF INFORMATION (Cite specific references. e.g., state files, sample analysis, reports)

New York Department of Conservation (DEC) Background File.

NUS Corp. Site Inspection conducted on 2/25/87, filed under TDD# 02-8612-11, Edison, NJ.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

VI. ENVIRONMENTAL INFORMATION

01 PERMEABILITY OF UNSATURATED ZONE (Check one)

☐ A. 10^{-6} - 10^{-8} cm/sec ☒ B. 10^{-4} - 10^{-6} cm/sec ☐ C. 10^{-4} - 10^{-3} cm/sec ☐ D. GREATER THAN 10^{-3} cm/sec

02 PERMEABILITY OF BEDROCK (Check one)

☐ A. IMPERMEABLE
(Less than 10^{-6} cm/sec) ☒ B. RELATIVELY IMPERMEABLE
(10^{-4} - 10^{-6} cm/sec) ☐ C. RELATIVELY PERMEABLE
(10^{-2} - 10^{-4} cm/sec) ☐ D. VERY PERMEABLE
(Greater than 10^{-2} cm/sec)

03 DEPTH TO BEDROCK

Approx. 40 (ft)

04 DEPTH OF CONTAMINATED SOIL ZONE

6 (ft)

05 SOIL pH

Unknown

06 NET PRECIPITATION

1.5 (in)

07 ONE YEAR 24 HOUR RAINFALL

2.6 (in)

08 SLOPE

SITE SLOPE

8 %

DIRECTION OF SITE SLOPE

North West

TERRAIN AVERAGE SLOPE

8 %

09 FLOOD POTENTIAL

10

Not Applicable

SITE IS IN Unknown YEAR FLOODPLAIN

SITE IS ON BARRIER ISLAND, COASTAL HIGH HAZARD AREA, RIVERINE FLOODWAY

11 DISTANCE TO WETLANDS (5 acre minimum)

ESTUARINE

OTHER

A. N/A (mi)

B. 0 (mi)

12 DISTANCE TO CRITICAL HABITAT (of endangered species)

Greater than 1 (mi)

ENDANGERED SPECIES:

N/A

13 LAND USE IN VICINITY

DISTANCE TO:

COMMERCIAL/INDUSTRIAL

RESIDENTIAL AREAS: NATIONAL/STATE PARKS,
FORESTS, OR WILDLIFE RESERVES

AGRICULTURAL LANDS
PRIME AG LAND

AG LAND

A. 2 (mi)

B. 0.25 (mi)

Approx.
C. 0.5 (mi)

D. 0.5 (mi)

14 DESCRIPTION OF SITE IN RELATION TO SURROUNDING TOPOGRAPHY

The site is relatively level, sloping gently to the northwest. It is situated adjacent to a wetland through which a permanent stream runs. Two lakes are located approximately 1500 ft. west and upgradient of the site.

VII SOURCES OF INFORMATION (Cite specific references e.g., state files, sample analysis, reports)

U.S. Geological Survey Topographic Map - Amenia, New York.
Groundwater Resources of Dutchess County, New York, New York Water Resources Commission, 1961.
HRS Users Manual, MITRE Corporation for U.S. EPA, 1984.
Interpretative soils report, Dutchess County, U.S. Department of Agriculture, 1978.
GEMS Graphical Exposure Modeling System.
New York State Critical Habitat Overlays.

EPA FORM 2070-13 (7-81)

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 6 - SAMPLE AND FIELD INFORMATION

I. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. SAMPLES TAKEN

SAMPLE TYPE	01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	03 ESTIMATED DATE RESULTS AVAILABLE
GROUNDWATER	3	Organic Lab:	
SURFACE WATER	3	Clayton Environmental Consultants, Inc. 22345 Roethel Drive Novi, MI 48050	7/87
WASTE			
AIR			
RUNOFF			
SPILL		Inorganic Lab:	
SOIL	4	Versar, Inc. 6850 Versar Center Springfield, VA 22151	7/87
VEGETATION			
OTHER			

DRAFT

III. FIELD MEASUREMENTS TAKEN

01 TYPE	02 COMMENTS
OVA	40 ppm on soil pile where NY66-S-1 was taken.

IV. PHOTOGRAPHS AND MAPS

01 TYPE	<input checked="" type="checkbox"/> GROUND <input type="checkbox"/> AERIAL	02 IN CUSTODY OF	NUS Corporation, FIT 2 (Name of organization or individual)
03 MAPS	04 LOCATION OF MAPS		
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	NUS Corporation, Edison, NJ		

V. OTHER FIELD DATA COLLECTED (Provide narrative description)

Field notebook #0030, dated 2/25/87

VI. SOURCES OF INFORMATION (Cite specific references. e.g., state files, sample analysis, reports)

NUS Corporation Site Inspection conducted on 2/25/87, filed under TOD #02-8612-11, Edison, NJ.

SITE INSPECTION REPORT
PART 7 - OWNER INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. CURRENT OWNER(S)

II. CURRENT OWNER(S)			PARENT COMPANY (If applicable)		
01 NAME	02 D + B NUMBER	08 NAME	09 D + B NUMBER		
John Segalla		N/A			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD#, etc.)	11 SIC CODE		
Leedsville Road					
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE
Amenia	NY	12501			

01 NAME	02 D + B NUMBER	08 NAME	09 D + B NUMBER		
Karl Saliter					
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD#, etc.)	11 SIC CODE		
Box 128, Jackson Hill Road					
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE
Sharon	CT	06069			

01 NAME	02 D + B NUMBER	08 NAME	09 D + B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD#, etc.)	11 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE

01 NAME	02 D + B NUMBER	08 NAME	09 D + B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	10 STREET ADDRESS (P.O. Box, RFD#, etc.)	11 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE

III. PREVIOUS OWNER(S) (List most recent first)

01 NAME	02 D + B NUMBER	04 SIC CODE	07 ZIP CODE
Murphy Brothers			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)			
05 CITY	06 STATE		

IV. REALTY OWNER(S) (If applicable; list most recent first)

01 NAME	02 D + B NUMBER	04 SIC CODE	07 ZIP CODE
03 STREET ADDRESS (P.O. Box, RFD#, etc.)			
05 CITY	06 STATE		

01 NAME	02 D + B NUMBER	04 SIC CODE	07 ZIP CODE
Mr. Surico			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)			
05 CITY	06 STATE		

01 NAME	02 D + B NUMBER	04 SIC CODE	07 ZIP CODE
Town of Amenia and the Town of Sharon			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)			
05 CITY	06 STATE		

V. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

New York Department of Conservation (DEC) Background File.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 8 - OPERATOR INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

II. CURRENT OPERATOR(S)			OPERATOR'S PARENT COMPANY (If applicable)		
01 NAME	02 D + B Number	10 NAME	11 D + B NUMBER		
Sharon Oil Co.		N/A			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD#, etc.)	13 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE
Amenia	NY				
08 YEARS OF OPERATION	09 NAME OF OWNER				
Presently used	Karl Saliter				

III. PREVIOUS OPERATOR(S) (List most recent first: Provide only if different from owner)			PREVIOUS OPERATOR'S PARENT COMPANIES (If applicable)		
01 NAME	02 D + B Number	10 NAME	11 D + B NUMBER		
		N/A			
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD#, etc.)	13 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE
08 YEARS OF OPERATION	09 NAME OF OWNER				

DRAFT

01 NAME	02 D + B Number	10 NAME	11 D + B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD#, etc.)	13 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE
08 YEARS OF OPERATION	09 NAME OF OWNER				

01 NAME	02 D + B Number	10 NAME	11 D + B NUMBER		
03 STREET ADDRESS (P.O. Box, RFD#, etc.)	04 SIC CODE	12 STREET ADDRESS (P.O. Box, RFD#, etc.)	13 SIC CODE		
05 CITY	06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE
08 YEARS OF OPERATION	09 NAME OF OWNER				

IV. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

New York Department of Conservation (DEC) Background File.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 9 - GENERATOR/TRANSPORTER INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

II ON-SITE GENERATOR

01 NAME 02 D + B NUMBER

N/A

03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE

05 CITY 06 STATE 07 ZIP CODE

III OFF-SITE GENERATOR(S)

01 NAME 02 D + B NUMBER 01 NAME 02 D + B NUMBER

N/A

03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE 03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE

05 CITY 06 STATE 07 ZIP CODE 05 CITY 06 STATE 07 ZIP CODE

01 NAME 02 D + B NUMBER 01 NAME 02 D + B NUMBER

03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE 03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE

05 CITY 06 STATE 07 ZIP CODE 05 CITY 06 STATE 07 ZIP CODE

IV. TRANSPORTER(S)

01 NAME 02 D + B NUMBER 01 NAME 02 D + B NUMBER

N/A

03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE 03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE

05 CITY 06 STATE 07 ZIP CODE 05 CITY 06 STATE 07 ZIP CODE

01 NAME 02 D + B NUMBER 01 NAME 02 D + B NUMBER

03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE 03 STREET ADDRESS (P.O. Box, RFD#, etc.) 04 SIC CODE

05 CITY 06 STATE 07 ZIP CODE 05 CITY 06 STATE 07 ZIP CODE

V. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 10 - PAST RESPONSE ACTIVITIES

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

II. PAST RESPONSE ACTIVITIES

01 A. WATER SUPPLY CLOSED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 B. TEMPORARY WATER SUPPLY PROVIDED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 C. PERMANENT WATER SUPPLY PROVIDED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 D. SPILLED MATERIAL REMOVED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 E. CONTAMINATED SOIL REMOVED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 F. WASTE REPACKAGED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 G. WASTE DISPOSED ELSEWHERE
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 H. ON SITE BURIAL
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

During NUS site inspection, three 55-gallon drums were observed on the landfill.

01 I. IN SITU CHEMICAL TREATMENT
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 J. IN SITU BIOLOGICAL TREATMENT
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 K. IN SITU PHYSICAL TREATMENT
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 L. ENCAPSULATION
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 M. EMERGENCY WASTE TREATMENT
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 N. CUTOFF WALLS
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 O. EMERGENCY DIKING/SURFACE WATER DIVERSION
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 P. CUTOFF TRENCHES/SUMP
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 Q. SUBSURFACE CUTOFF WALL
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

DRAFT

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 10 - PAST RESPONSE ACTIVITIES

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY 0980641559

II. PAST RESPONSE ACTIVITIES

01 R. BARRIER WALLS CONSTRUCTED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 S. CAPPING/COVERING
04 DESCRIPTION

02 DATE: 1975

03 AGENCY: _____

At final closure in 1975, the main fill area received a soil cover applied by a local contractor.

01 T. BULK TANKAGE REPAIRED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 U. GROUT CURTAIN CONSTRUCTED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 V. BOTTOM SEALED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 W. GAS CONTROL
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 X. FIRE CONTROL
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 Y. LEACHATE TREATMENT
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 Z. AREA EVACUATED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 1. ACCESS TO SITE RESTRICTED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 2. POPULATION RELOCATED
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

01 3. OTHER REMEDIAL ACTIVITIES
04 DESCRIPTION

02 DATE: _____

03 AGENCY: _____

No Previous History.

DRAFT

III. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, reports)

New York State Department of Conservation (DEC) Background File.

POTENTIAL HAZARDOUS WASTE SITE
SITE INSPECTION REPORT
PART 11 - ENFORCEMENT INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
NY D980641559

II. ENFORCEMENT INFORMATION

01 PAST REGULATORY/ENFORCEMENT ACTION

☒ YES

☐ NO

02 DESCRIPTION OF FEDERAL, STATE, LOCAL REGULATORY/ENFORCEMENT ACTION

The Town of Amenia forced the closure of the site in January, 1969. The southern section of the site was reopened and operated by the Town of Amenia and the Town of Sharon, Connecticut until it was finally closed in 1975.

DRAFT

III. SOURCES OF INFORMATION (Cite specific references, e.g., state files, sample analysis, report)

New York Department of Conservation (DEC) Background File.